# SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department of Transportation

Federal Aviation Administration

No. CE-01-16 February 16, 2001

# Aircraft Certification Service Washington, DC

# We post SAIBs on the internet at "av-info.faa.gov"

This is information only. Recommendations are not mandatory.

#### Introduction

This Special Airworthiness Information Bulletin advises you, an owner and operator, of SOCATA TBM series airplanes of the need to review the service bulletin listed below.

# **Background**

The FAA's Small Airplane Directorate conducted a review of specified SOCATA TBM series airplanes service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included: Mandated compliance by initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Owners/operators of SOCATA TBM series airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

### Recommendations

The service bulletin identified in this document is not considered appropriate for AD action at this time, however, the FAA strongly suggests that all owners/operators of the SOCATA TBM series airplanes review their compliance with the service bulletin listed below.

SOCATA TBM Airplane Series			
Service Bulletin Number	MODEL	DATE	TITLE
SB 70-089	TBM 700	12/00	Nose Gear Tire

## The Service Bulletins Can Be Obtained From

SOCATA Aircraft, Groupe Aerospatiale North Perry Airport 7501 Pembroke Road Pembroke Pines, FL 33023 954-893-1400 phone 954-964-4141 facsimile

### **For Further Information Contact**

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 901 Locust Street, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov